G. R. S. 59] G1 B—15,000—20 12 13

GENERAL AND REVENUE SECRETARIAT.

1895-6
191.
(Inward)

File No. 106

Serial Nos.

Papers Filed.

*Month*_____

SUBJECT.

Sanctioning the payment of a sum of Rs 126-2-4 for repairs executed to the Kitchen & Ramanuja Koottam Mantaps attached to the Sri Ranganathaswami Temple at Srirangapatam -

PREVIOUS REFERENCES	LATER REFERENCES.

Read

~~Report~~ No. 625 dated

13th April/96 from the

Amildar of the Srirangapatam Taluk soliciting

sanction to a sum of

Rs. 126-2-4, being the

cost of repairs executed

to the Ketchen and

Ramanuja Kootam

Mantap attached to

the Shri Ranganatha-

swami temple at Seran-

gapatam and ~~d~~ sub-

mitting for countersignature

and transmission to the

Comptroller for audit

a measurement list for

the amount

√P

No. 1110-1
Mun 7 138.92 dy 28/4/96

Order thereon —

During his late inspec-

tion, the Manjrasi Superin-

tendent

found that the Ketchen

and the Ramanuja Kootam

referred to above

Mantap were in urgent

need of repairs and gave

personal instructions to

to the Amildar of Srirangapatam for the immediate execution thereof ~~and [illegible]~~.

(2)

The Amildar carried out the repairs accordingly and now submits a measurement list for the amount.

2. The cost of Rs. 126-2-4 for work amounting to is sanctioned, the charge being met from the State grant of Rs. 15000/ sanctioned in Govt. Proc. No. 74-9 M R 105-92 dated 25th Feby/95 for the repairs of Muzrai institutions in the Province for the year 1895-96.

3. The measurement list for Rs. 126-2-4 is Countersigned and forwarded to the Comptroller for audit and immediate return to the Amildar of Srirangapatam for

(1) for payment. The amount should be made payable on the aforesaid Taluk Treasury.

Manjrai Rao
C.T.

To The Amildar of the Seringapatam Taluk.

— in Comptroller, Mysore Govt's, with the measurement list.